Westhertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/18018UE-1786/1

Work Order Type: Weatherization Audit Name: 18018UE-1786

CLIENT INFORMATION

Client Name: Address:

Client ID: 18018UE-1786

Alt. Client ID: Johnson

<u>AGENCY INFORMATION</u>

Agency: Upper East Tennessee Human Development Agency Agency Phone: 246-6180

Address: 301 Louis Street Fax:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Trailer 14 x 70=940 ducts need masitic (9) need (8) Registers Bellyboard has 100 sq.repairs No ground cover and belly in fair shape. Has need of front door unit and W/S back door all window need caulking inside ceiling in water heater closet need repair 5 sq.ft. Top sash in window front room need repaired 3ft by 2inches.. Base of window need repaired 3ft. X 2 inches. Has mold in I coner of and back of washer needs repair 6sq. Ft. Air seal plumbing in bath (20 and kitchen. Repair hole in wall protrusin 3ft x 2" long. And seal and repair of under sink. Repair ceiling in bath 3 sq.ft.

Client Name:
Client ID: 18018UE-1786
Alt. Client ID: Johnson

CFM 2543 @ 50.1 target 1801.8

Work Order (Bid Form)
Work Order Name: WO/18018UE-1786/1

Report Run On: 3/30/2012

DOE Weatherization Assistant

Version 8.6.0 Page 1 of 8

Measures

	Measure 1 Seal	Ducts			Componen	ts			Inspected
C	omment				Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	Duct sealing (setup cost)	Each	9					
1	Miscellaneous Su	Duct Sealing	Hour	1					
2	Miscellaneous Su	Replace 8 Duct register	Each	8					
2	Labor	install floor register	Hour	1					
3	Miscellaneous Su	Repair Ceiling in bath (2 sq ft.)	SqFt	2					
3	Labor	Repair Ceiling bath	Hour	2					
4	Construction Mate	Repair ceiling H2O closet	SqFt	4					
4	Labor	Repair 4 sq. ft. ceiling	Hour	2					
5	Miscellaneous Su	Repair Seal living room window (3' x 2")	Each	1					
5	Labor	Repair Seal (upper seal)	Hour	1					
6	Labor	Replace wood	Hour	1					
6	Miscellaneous Su	replace wood on bottom seal (3' x 2")	Each	1					
7	Construction Mate	Replace wood in wash room behind at hook up 3 sq.ft.	SqFt	3					
7	Labor	Labor to install 3 sq.ft.	Hour	1					
8	Miscellaneous Su	repair missing wood (Kitchen)	Each	1					
8	Labor	Replace wood (3' x 2")	Hour	2					
9	Labor	caulk interior of window (9)	Each	9					
9	Miscellaneous Su	caulk windows	Each	9					

Other Detail								
]		
]		
			Measur	e Sub Total:		;	Sub Total:	
Field Notes:								
Measure 2 Re	eplace refrigerator			Componen	ts		ļ	Inspected
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Refrigerators	Replace refrigerator	Each	1					
-						,		
1 Labor	refregerator installation	Each	1					
Other Detail								
Other Detail								
] []		
			Measur	e Sub Total:		,	Sub Total:	
F								
Field Notes:								

Measure 3 Lig Comment	phting [Kitche][2]			Componen				nspected
# Matarial / Labor	December / Comment	Unito		Estimated			Actual	Total
# Material / Labor	Description / Comment	Units _	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor	Compact Fl13 Watt	Each	2					
1 Lighting	Compact Fl13 Watt	Each	2					
Other Detail								
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 4 Lig	hting [Bedroo][2]			Componen				nspected
Comment				Estimated			Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected
Comment # Material / Labor		<i>Units</i> Each	Qty 2	Estimated		Qty	Actual	
Comment # Material / Labor 1 Lighting	Description / Comment		_	Estimated		Qty	Actual	
# Material / Labor Lighting Labor	Description / Comment Compact Fl13 Watt	Each	2	Estimated		Qty	Actual	
Comment # Material / Labor 1 Lighting	Description / Comment Compact Fl13 Watt	Each	2	Estimated		Qty	Actual	
# Material / Labor Lighting Labor	Description / Comment Compact Fl13 Watt	Each	2	Estimated		Qty	Actual	
Comment# Material / Labor1 Lighting1 Labor	Description / Comment Compact Fl13 Watt	Each	2 2	Estimated			Actual	

Actual Qty Unit Cost Total	Total	Estimated Unit Cost	Qty 2	<i>Units</i> Each	Description / Comment Compact Fl13 Watt	omment Material / Labor
-			2			
				Each	Compact EL -13 Watt	
					Compact 1113 Watt	Lighting
			2	Each	Compact Fl13 Watt	Labor
						Other Detail
Sub Total:		e Sub Total:	Measur			
Inspected		Component			hting [Dining][2]	Measure 6 Ligl comment
Actual	 -					
Qty Unit Cost Total	Total	Unit Cost	_			
			2	Each	Compact Fl13 Watt	Lighting
			2	Each	Compact Fl13 Watt	Labor
						Other Detail
Sub Total:		re Sub Total:				
		Estimated Unit Cost	Qty 2	<i>Units</i> Each Each	Description / Comment Compact Fl13 Watt	Material / Labor Lighting Labor

Measure 7 Lig	hting [Bathro][1]			Componen	ts LT6		,	Inspecte
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor	Compact Fl13 Watt	Each	1					
Lighting	Compact Fl13 Watt	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 8 Lig	hting [Bathro][2]			Componen				Inspecte
Measure 8 Lig		Units	Qtv	Estimated		Ofv	Actual	
Measure 8 Lig Comment # Material / Labor	hting [Bathro][2] Description / Comment Compact Fl13 Watt	<i>Units</i> Each	Qty 2	•		Qty		Inspecte
Measure 8 Lig Comment Material / Labor Lighting	Description / Comment		_	Estimated		Qty	Actual	
Measure 8 Lig Comment Material / Labor Lighting Labor	Description / Comment Compact Fl13 Watt	Each	2	Estimated		Qty	Actual	
Measure 8 Lig Comment # Material / Labor 1 Lighting	Description / Comment Compact Fl13 Watt	Each	2	Estimated		Qty	Actual	
Measure 8 Lig Comment # Material / Labor 1 Lighting 1 Labor	Description / Comment Compact Fl13 Watt	Each	2	Estimated			Actual Unit Cost	
Measure 8 Lig Comment # Material / Labor 1 Lighting 1 Labor	Description / Comment Compact Fl13 Watt	Each Each	2 2	Estimated			Actual	
Measure 8 Lig Comment # Material / Labor 1 Lighting 1 Labor	Description / Comment Compact Fl13 Watt	Each Each	2 2	Estimated Unit Cost			Actual Unit Cost	

	Measure 9 Belly omment	/ Fiberglass Loose			Componen	ts		1	Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fbergls,Blwn	SqFt	100					
1	Labor	Floor Insulation - Fbergls,Blwn	SqFt	100					
0	Other Detail						1		
L									
] []	Sub Total:	
				Measur	e Sub Total:		•	Sub Total.	
	Measure 10 Smo	ke Detector is Needed			Componen				Inspected
C	omment		Unito		Estimated		- O4:	Actual	
<i>C</i>	omment Material / Labor	Description / Comment	Units Fach	Qty	-		Qty		Inspected
<i>C</i>	omment	Description / Comment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
C # 1	omment Material / Labor	Description / Comment			Estimated		Qty	Actual	
C **	omment Material / Labor Health and Safety	Description / Comment Smoke detector	Each	1	Estimated		Qty	Actual	
C **	omment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	1	Estimated		Qty	Actual	
C **	omment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each Each	1	Estimated Unit Cost			Actual Unit Cost	
# 1 1 <u>0</u>	omment Material / Labor Health and Safety Labor Other Detail	Description / Comment Smoke detector	Each Each	1	Estimated			Actual	
# 1 1 O	omment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each Each	1	Estimated Unit Cost			Actual Unit Cost	

Measure 10 Replace Doors Mandatory					Components DR1				
C	Comment								
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Doors	Replacement doors	Each	1					
1	Labor	Replacement doors	Each	1					
(Other Detail			1	1		1		
				Measur	e Sub Total:] .	Sub Total:	
	Field Notes:								
ı									
			Work Or	der Gra	nd Total:		Gran	d Total:	